


ACTIVE COMPONENTS®
OSU & Stanchion Assembly
 Installation Instructions


0 1/2 1
 1/4 1/4

Scale 1 : 1


Tools Required



PARTS



STANCHION/SUPPORT LOCATION FOR NOOK



CUSTOMER SERVICE PHONE: 1-800-426-8562

HAWORTH®


E.C.O. No: 355-048

Page: 1 of 6

Part No: 7029-9961

Rev: 2

STANCHION/SUPPORT LOCATION FOR SHELF




1

(F)

#10-16 x 7/16" Pan Head

IMPORTANT

ALL SCREWS (F) MUST BE
INSTALLED BY HAND!
(VERY LOW TORQUE)



CUSTOMER SERVICE PHONE: 1-800-426-8562

HAWORTH®

E.C.O. No: 355-048



Page: 2 of 6

Part No: 7029-9961

Rev: 2

WORKSURFACE MOUNTING




2a



OR

INTUITY RAIL MOUNTING

2b



CUSTOMER SERVICE PHONE: 1-800-426-8562

HAWORTH®

E.C.O. No: 355-048

Page: 3 of 6

Part No: 7029-9961

Rev: 2




RESIDE MOUNTING

2c

! IMPORTANT




ALL SCREWS (F) MUST BE
INSTALLED BY HAND!
(VERY LOW TORQUE)




INTUITY - STABILIZER BRACKET (OPTIONS) AND ASSEMBLY ORDER


1 Attach stanchion's and stabilizer brackets




2 Remove worksurfaces



3 Install overhead



4 Reinstall worksurfaces



CUSTOMER SERVICE PHONE: 1-800-426-8562

HAWORTH®



E.C.O. No: 355-048

Page: 4 of 6

Part No: 7029-9961

Rev: 2

STABILIZER BRACKET (OPTIONS)








IMPORTANT



ALL SCREWS (F) MUST BE
INSTALLED BY HAND!
(VERY LOW TORQUE)

NOTE: Stabilizer is not
required for 8" high units.



CUSTOMER SERVICE PHONE: 1-800-426-8562

HAWORTH®

E.C.O. No: 355-048

Page: 5 of 6

Part No: 7029-9961



Rev: 2

STABILIZER BRACKET (OPTIONS)


! IMPORTANT





ALL SCREWS (F) MUST BE
INSTALLED BY HAND!
(VERY LOW TORQUE)







WITH HATCH



WITHOUT HATCH



NOTE: Stabilizer is
not required for 8"
high units.



NOTE: Any screw added
must have a clearance/pilot
hole where applicable.

CUSTOMER SERVICE PHONE: 1-800-426-8562

HAWORTH®

E.C.O. No: 355-048

Page: 6 of 6

Part No: 7029-9961

Rev: 2